

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 12/4/2013      **Time:** 8:46 AM  
**Name of School Corporation:** KID CO CHILDCARE (41)      **Corp ID:** 41DC3  
**Address of School Corporation:** 2503 Fairview Place Suite A  
**City:** Greenwood      **Zip:** 46142      **County Number:** 41  
**VIN:** 1GBHG31R3Y1250694      **License Number:** B785AB      **Bus Number:** 4  
**Make of Body:** Chevrolet      **Year:** 2000      **Make of Chassis:** Chevrolet      **Year:** 2000  
**Bus Type:** A1      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Chris Kath      **PE:** 6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
33-1-1	Headlight is inoperative.
21-1-4	There is a significant fluid leak from the transmission.
15-1-1	There are leaks from the differential, pinion seal, or either rear wheel seal.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, the certification has expired, or is not signed within the six month requirement.
63-2-1	Rear turn signal does not function properly

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.