

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 12/16/2013	Time: 1:51 PM
Name of School Corporation: EASTERN GREENE SCHOOLS	Corp ID: 282940	
Address of School Corporation: RR 4 Box 351		
City: Bloomfield	Zip: 47424	County Number: 28
VIN: 4DRBUAFP58B499459	License Number: 75065	Bus Number: 11
Make of Body: IC Corporation	Year: 2008	Make of Chassis: IC Corporation
Year: 2008	Mileage: Unknown	Year: 2008
Bus Type: C		
Inspection Status: O	Inspected By: Mark Raper	PE: 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
66-1-2	Rims are bent or loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
52-2-1	Broken main leaf in a leaf spring.
52-2-5	"U" bolts are loose, broken, or missing
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.