

## REPORT OF SCHOOL BUS INSPECTION

|                                                               |                                    |                                   |
|---------------------------------------------------------------|------------------------------------|-----------------------------------|
| <b>Type of Inspection:</b> Spot Checks                        | <b>Date:</b> 12/17/2013            | <b>Time:</b> 8:58 AM              |
| <b>Name of School Corporation:</b> ORLEANS COMMUNITIY SCHOOLS | <b>Corp ID:</b> 596145             |                                   |
| <b>Address of School Corporation:</b> 173 W Marley St         |                                    |                                   |
| <b>City:</b> Orleans                                          | <b>Zip:</b> 47452                  | <b>County Number:</b> 59          |
| <b>VIN:</b> 1GBJG31K591115240                                 | <b>License Number:</b> 76556       | <b>Bus Number:</b> 21             |
| <b>Make of Body:</b> Collins Bus Corporation                  | <b>Year:</b> 2009                  | <b>Make of Chassis:</b> Chevrolet |
| <b>Bus Type:</b>                                              | <b>Mileage:</b> Unknown            | <b>Year:</b> 2009                 |
| <b>Inspection Status:</b> A                                   | <b>Inspected By:</b> Kelly Hammond | <b>PE:</b> 6682                   |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|