

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/16/2014	Time:	12:48 PM
Name of School Corporation:	MERRILLVILLE COMM. SCHOOL CORP	Corp ID:	454600		
Address of School Corporation:	6601 Delaware St				
City:	Merrillville	Zip:	46410	County Number:	45
VIN:	4DRBUAAN69B051982	License Number:	32529	Bus Number:	13
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation
Year:	2009		Year:	2009	
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	David Eggers	PE:	5191

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-1	The service door does not open or close properly
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.