

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 1/16/2014 Time: 12:48 PM
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP Corp ID: 454600
Address of School Corporation: 6601 Delaware St
City: Merrillville Zip: 46410 County Number: 45
VIN: 4DRBUAAN69B051982 License Number: 32529 Bus Number: 13
Make of Body: IC Corporation Year: 2009 Make of Chassis: IC Corporation Year: 2009
Bus Type: C Mileage: Unknown
Inspection Status: O Inspected By: David Eggers PE: 5191

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-1	The service door does not open or close properly
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.