

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/23/2014	Time:	2:15 PM		
Name of School Corporation:	EASTERN GREENE SCHOOLS			Corp ID:	282940		
Address of School Corporation:	RR 4 Box 351						
City:	Bloomfield	Zip:	47424	County Number:	28		
VIN:	4DRBRAAP93B952080		License Number:	B127E	Bus Number:	3	
Make of Body:	IC Corporation	Year:	2003	Make of Chassis:	IC Corporation	Year:	2003
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Mark Raper	PE:	6473		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
11-1-1	The front bumper does not extend to the edge of the fenders.
11-1-2	The front or rear bumper is not properly attached.
56-1-2	Step-well area is weakened
56-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.