

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 1/23/2014	<b>Time:</b> 2:15 PM
<b>Name of School Corporation:</b> EASTERN GREENE SCHOOLS	<b>Corp ID:</b> 282940	
<b>Address of School Corporation:</b> RR 4 Box 351		
<b>City:</b> Bloomfield	<b>Zip:</b> 47424	<b>County Number:</b> 28
<b>VIN:</b> 4DRBRAAP93B952080	<b>License Number:</b> B127E	<b>Bus Number:</b> 3
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2003	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2003	<b>Mileage:</b> Unknown	<b>Year:</b> 2003
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Mark Raper	<b>PE:</b> 6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
11-1-1	The front bumper does not extend to the edge of the fenders.
11-1-2	The front or rear bumper is not properly attached.
56-1-2	Step-well area is weakened
56-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**