REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	2/7/2014	Time:	1:18 PM
Name of Schoo Address of Sch	I Corporation: LA	APORTE COMM 1921 A St	IUNITY SCHOOL	CORP.	Corp ID:	464945
City:	La Porte	Zip:	46350		County Number:	46
VIN:	4UZABRDT5ACAR0946	-	License Number:	74230	Bus Number:	63
Make of Body:	Thomas Built Buses, Ye Inc.	ear: 2010	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2010
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	Nathan Sherer		PE:	7029

Violations - Rejected

Inspection Code	Description
33-1-1	Headlight is inoperative.

Violations - Out of Service

Inspection <u>Code</u>	Description
24-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.