

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/7/2014	Time:	1:18 PM
Name of School Corporation:	LAPORTE COMMUNITY SCHOOL CORP.			Corp ID:	464945
Address of School Corporation:	200 Stevens				
City:	La Porte	Zip:	46350	County Number:	46
VIN:	4UZABRDT5ACAR0946			Bus Number:	63
Make of Body:	Thomas Built Buses, Inc.	Year:	2010	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	Unknown
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-1	Headlight is inoperative.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.