

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/17/2014 **Time:** 9:48 AM
Name of School Corporation: NORTH MONTGOMERY COMM SCH CORP **Corp ID:** 545835
Address of School Corporation: 480 W 580 N
City: Crawfordsville **Zip:** 47933 **County Number:** 54
VIN: 4DRBUAAN8BB334289 **License Number:** 8893 **Bus Number:** 1
Make of Body: IC Corporation **Year:** 2011 **Make of Chassis:** IC Corporation **Year:** 2011
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.