

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/19/2014	Time:	11:26 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION			Corp ID:	848030
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBWAARXAA176670	License Number:	32777	Bus Number:	930
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation
Bus Type:	D	Mileage:	Unknown	Year:	2010
Inspection Status:	O	Inspected By:	Tyler VanNess	PE:	7583

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
56-1-5	Step-well light is missing or inoperative
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
61-2-1	Two (2) or more taillights or brake lights do not function
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.