

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 2/19/2014      **Time:** 12:49 PM  
**Name of School Corporation:** NORTH DAVIESS CO. COMM. SCHOOL      **Corp ID:** 141375  
**Address of School Corporation:** 5494 E SR 58  
**City:** Elnora      **Zip:** 47529      **County Number:** 14  
**VIN:** 4UZAAXBV62CJ97773      **License Number:** D784792      **Bus Number:** 16  
**Make of Body:** Freightliner      **Year:** 2002      **Make of Chassis:** Freightliner      **Year:** 2002  
**Bus Type:** C      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Kelly Hammond      **PE:** 6682

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

24-2-1      Mountings are broken or bent badly enough to inhibit proper adjustment.  
24-2-2      Reflective glass is cracked, broken, or missing.  
58-2-4      Stop arm does not function properly

#### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**