REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	2/20/2014	Time:	11:03 AM
Name of School Co	orporation: EL	WOOD COMMUN	ITY SCHOOL COR	P.	Corp ID:	485280
Address of School	Corporation:	1306 N Anders	on St			
City:	Elwood	Zip:	46036		County Number:	48
VIN:	4DRBUSKP59B6	73964	License Number:	32109	Bus Number:	2
Make of Body:	IC Corporation Ye	ar: 2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	В		Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Jeremy Mason		PE:	8139

Violations - Rejected

Inspection Code	Description
56-1-5	Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.