# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Re-Inspection | **Date:** | 2/21/2014 | **Time:** | 8:38 AM |
| **Name of School Corporation:** | ELWOOD COMMUNITY SCHOOL CORP. | | | **Corp ID:** | 485280 |
| **Address of School Corporation:** | 1306 N Anderson St | | | | |
| **City:** | Elwood | **Zip:** | 46036 | **County Number:** | 48 |
| **VIN:** | 4DRBUSKP59B673964 | **License Number:** | 32109 | **Bus Number:** | 2 |
| **Make of Body:** | IC Corporation **Year:** 2009 | **Make of Chassis:** | IC Corporation | **Year:** | 2009 |
| **Bus Type:** | B | **Mileage:** | Unknown | | |
| **Inspection Status:** | A | **Inspected By:** | Jeremy Mason | **PE:** | 8139 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**