## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/28/2014Time:1:11 PMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City:BedfordZip:47421County Number:47VIN:4DRBUAAP18A499505License Number:Bus Number:4SHMake of Body:IC Corporation Year:2008Make of Chassis:IC Corporation Year:2008

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: Travis Coryea PE: 5892

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

Rear tire has less than 2/32 inch tread depth when measured in a major groove.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.