REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/4/2014	**Time:**	10:31 AM
Name of School Corporation:	KOKOMO SCHOOL CORPORATION			**Corp ID:**	343500
Address of School Corporation:	620 W Deffenbaugh				
City:	Kokomo	**Zip:**	46901	**County Number:**	34
VIN:	1FDWE35P66HA03798	**License Number:**	21218	**Bus Number:**	108
Make of Body:	Ford **Year:** 2006	**Make of Chassis:**	Ford	**Year:**	2006
Bus Type:	A2	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
40-1-4	There is debris in the bus. (needs cleaned) includes dirt
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
64-1-1	Lens is cracked, broken or discolored

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**