## **REPORT OF SCHOOL BUS INSPECTION**

| Type of Inspection:                          | Annual              |               | Date:            | 3/4/2014 | Time:          | 11:36 AM |
|--|---------------------|---------------|------------------|----------|----------------|----------|
| Name of School Co                            | orporation: GRIF    | FITH PUBLIC S | CHOOLS           |          | Corp ID:       | 454700   |
| Address of School Corporation: 602 N Raymond |                     |               |                  |          |                |          |
| City:  | Griffith            | Zip:          | 46319            |          | County Number: | 45       |
| VIN:   | 1FDWE35P46HB24      | 4040          | License Number:  | 71026    | Bus Number:    | 26       |
| Make of Body:                                | Mid Bus, Inc. Year: | 2006          | Make of Chassis: | Ford     | Year:          | 2006     |
| Bus Type:                                    |                     |               | Mileage:         | Unknowr  | ı              |          |
| Inspection Status:                           | 0                   | Inspected By: | Nathan Sherer    |          | PE:            | 7029     |

## Violations - Rejected

| Inspection Code | Description   |
|-----------------|---|
| 24-1-1          | Mirror or mirror backs are loose or improperly mounted. |
| 27-1-2          | The first aid kit is not properly filled.               |

## Violations - Out of Service

| Inspection Code | <b>Description</b>                           |
|-----------------|--|
| 49-2-1          | There is no seat belt cutter in the vehicle. |

## **Bus Type Description**