

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	3/5/2014	<b>Time:</b>	10:35 AM
<b>Name of School Corporation:</b>	FRANKLIN COUNTY COMM. SCH CORP			<b>Corp ID:</b>	242475
<b>Address of School Corporation:</b>	225 E 10th St				
<b>City:</b>	Brookville	<b>Zip:</b>	47012	<b>County Number:</b>	24
<b>VIN:</b>	4DBRUAAN5CB591878	<b>License Number:</b>	B538F	<b>Bus Number:</b>	1
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2012	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2012	<b>Year:</b>	2012	<b>Year:</b>	2012
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Chris Clark	<b>PE:</b>	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-1	The horn does not operate at all.
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
54-2-7	There are any cracks in any steering component.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**