REPORT OF SCHOOL BUS INSPECTION

Type of 1:48 Time: Annual Date: 3/5/2014 Inspection: РМ Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 1GBL7T1C71J508775 B121E **Bus Number:** 10 Number: Make of Blue Bird Blue Bird Year: 2002 Make of Body: Year: 2002 Corporation Chassis: Corporation Bus Type: С Mileage: Unknown Inspection Inspected R PE: 6682 Kelly Hammond Status: By:

Violations - Rejected

2-1-1 Required back-up lights do not function.

22-1-3 An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.