

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/6/2014	Time:	10:51 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4UZAAXBV62CJ97773	License Number:	D784792	Bus Number:	16
Make of Body:	Freightliner	Year:	2002	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	Unknown	Year:	2002
Inspection Status:	A	Inspected By:	Kelly Hammond	PE:	6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.