

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/6/2014	<b>Time:</b>	12:02 PM
<b>Name of School Corporation:</b>	BISHOP NOLL INSTITUTE			<b>Corp ID:</b>	45B970
<b>Address of School Corporation:</b>	1519 Hoffman St				
<b>City:</b>	Hammond	<b>Zip:</b>	46327	<b>County Number:</b>	45
<b>VIN:</b>	1GBJG31U261118576	<b>License Number:</b>	B204E	<b>Bus Number:</b>	B
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2005	<b>Year:</b>	2005	<b>Year:</b>	2005
<b>Bus Type:</b>	A2	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.
79-1-3	If equipped, the emergency warning buzzer does not sound.
54-1-1	Play can be measured at one (1) location on any steering component
62-1-3	Any front tire has less than 4/32 inch tread depth when measured in a major groove.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
69-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
8-2-1	There is no brake certification, the certification has expired, or is not signed within the six month requirement.

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.

