

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/7/2014	Time: 9:02 AM
Name of School Corporation: SOUTH DEARBORN COMM. SCH. CORP	Corp ID: 151600	
Address of School Corporation: 6109 Squire Place		
City: Aurora	Zip: 47001	County Number: 15
VIN: 4DRBRAAP73B952062	License Number:	Bus Number: 6
Make of Body: IC Corporation	Year: 2003	Make of Chassis: IC Corporation
Year: 2003	Mileage: Unknown	PE: 6665
Bus Type: D		
Inspection Status: R	Inspected By: Chris Clark	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
21-1-1	A dripping oil or fluid leak.
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.