

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/10/2014 **Time:** 10:34 AM
Name of School Corporation: LAKE CENTRAL SCHOOL CORP. **Corp ID:** 454615
Address of School Corporation: 8855 Wicker Ave
City: St John **Zip:** 46373 **County Number:** 45
VIN: 1HVBRABN42B941563 **License Number:** 18917 **Bus Number:** 23
Make of Body: IC Corporation **Year:** 2002 **Make of Chassis:** IC Corporation **Year:** 2002
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
51-1-1	There are loose, broken, or missing mountings

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
21-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.