

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/10/2014 **Time:** 8:21 AM
Name of School Corporation: BAUGO COMMUNITY SCHOOLS **Corp ID:** 202260
Address of School Corporation: 29125 CR 22 W
City: Elkhart **Zip:** 46517 **County Number:** 20
VIN: 4UZAAXCT44CL83649 **License Number:** 10295 **Bus Number:** 6
Make of Body: Freightliner **Year:** 2003 **Make of Chassis:** Freightliner **Year:** 2003
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Brian Bills **PE:** 5506

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.
22-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-5	There is brake fluid leaking at any point.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.