REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	3/10/2014	**Time:**	2:21 PM
Name of School Corporation:		LAKE CENTRAL SCHOOL CORP.				**Corp ID:**	454615
Address of School Corporation:		8855 Wicker Ave					
City:	St John	**Zip:**	46373			**County Number:**	45
VIN:	4DRBUAFN97B369567			**License Number:**	20518	**Bus Number:**	91
Make of Body:	IC Corporation	**Year:**	2007	**Make of Chassis:**	IC Corporation	**Year:**	2007
Bus Type:	C			**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Nathan Sherer			**PE:**	7029

Violations - Rejected

Inspection Code	Description
19-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code	Description
54-2-2	There is pitman arm movement on output shaft

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.