

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/10/2014	<b>Time:</b> 1:56 PM
<b>Name of School Corporation:</b> LAKE CENTRAL SCHOOL CORP.	<b>Corp ID:</b> 454615	
<b>Address of School Corporation:</b> 8855 Wicker Ave		
<b>City:</b> St John	<b>Zip:</b> 46373	<b>County Number:</b> 45
<b>VIN:</b> 4DRBUAFN77B369566	<b>License Number:</b> 20519	<b>Bus Number:</b> 8
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2007	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2007	<b>Mileage:</b> Unknown	<b>PE:</b> 7029
<b>Bus Type:</b> C	<b>Inspected By:</b> Nathan Sherer	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
56-1-5	Step-well light is missing or inoperative
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.
21-1-1	A dripping oil or fluid leak.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
54-2-2	There is pitman arm movement on output shaft

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**