REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 3/6/2014 Time: 12:42 PM

Name of School Corporation: CENTERVILLE-ABINGTON COMM SCHS Corp ID: 898360

Address of School Corporation: 116 W SOUTH ST

 City:
 CENTERVILLE
 Zip:
 47330
 County Number:
 89

 VIN:
 1HBRABN01LA938177
 License Number:
 17966
 Bus Number:
 3

Make of Body: Year: 2001 Make of Chassis: IC Corporation Year: 2001

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Jeremy Mason PE: 8139

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

51-1-2 Shock absorber is leaking fluid

Rear tire has less than 2/32 inch tread depth when measured in a major groove.

Violations - Out of Service

Inspection Code Description

There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.