

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 3/13/2014      **Time:** 3:51 PM  
**Name of School Corporation:** HAMILTON HEIGHTS SCHOOL CORP.      **Corp ID:** 293025  
**Address of School Corporation:** PO Box 469  
**City:** Arcadia      **Zip:** 46030      **County Number:** 29  
**VIN:** 1GB3G3BG2E1105701      **License Number:** D755100      **Bus Number:** 29  
**Make of Body:** Chevrolet      **Year:** 2014      **Make of Chassis:** Chevrolet      **Year:** 2014  
**Bus Type:**      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Alex Willis      **PE:** 4760

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
71-1-1	There is no rejection criteria for air conditioning.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-3	Tire is flat
51-2-1	Shock absorber is broken or missing
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description