

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/13/2014 **Time:** 3:51 PM
Name of School Corporation: HAMILTON HEIGHTS SCHOOL CORP. **Corp ID:** 293025
Address of School Corporation: PO Box 469
City: Arcadia **Zip:** 46030 **County Number:** 29
VIN: 1GB3G3BG2E1105701 **License Number:** D755100 **Bus Number:** 29
Make of Body: Chevrolet **Year:** 2014 **Make of Chassis:** Chevrolet **Year:** 2014
Bus Type: **Mileage:** Unknown
Inspection Status: O **Inspected By:** Alex Willis **PE:** 4760

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
71-1-1	There is no rejection criteria for air conditioning.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-3	Tire is flat
51-2-1	Shock absorber is broken or missing
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description