

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/14/2014	Time:	12:23 PM		
Name of School Corporation:	DUNELAND SCHOOL CORPORATION			Corp ID:	646470		
Address of School Corporation:	601 W MORGAN AVE						
City:	Chesterton	Zip:	46304	County Number:	64		
VIN:	4DRBUAAN07B378875		License Number:	30087	Bus Number:	31	
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2007
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	David Eggers	PE:	5191		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-3	Tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.