

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/14/2014 **Time:** 12:23 PM
Name of School Corporation: DUNELAND SCHOOL CORPORATION **Corp ID:** 646470
Address of School Corporation: 601 W MORGAN AVE
City: Chesterton **Zip:** 46304 **County Number:** 64
VIN: 4DRBUAAN07B378875 **License Number:** 30087 **Bus Number:** 31
Make of Body: IC Corporation **Year:** 2007 **Make of Chassis:** IC Corporation **Year:** 2007
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** David Eggers **PE:** 5191

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-3	Tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.