REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 3/20/2014 Time: 8:39 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS

Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:4DRBUAAN0AB182572License Number:32798Bus Number:109Make of Body:IC Corporation Year:2010Make of Chassis:IC Corporation Year:2010

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

56-1-5 Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.