

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 3/20/2014      **Time:** 12:43 PM  
**Name of School Corporation:** CITY BAPTIST SCHOOLS      **Corp ID:** 45B985  
**Address of School Corporation:** 4925 S Sohl Ave  
**City:** Hammond      **Zip:** 46327      **County Number:** 45  
**VIN:** 4UZABRCS86CU14582      **License Number:** b104e      **Bus Number:** 155  
**Make of Body:** Freightliner      **Year:** 2006      **Make of Chassis:** Freightliner      **Year:** 2006  
**Bus Type:** D      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** David Eggers      **PE:** 5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.
52-2-4	Shackles are worn, loose, broken, cracked or missing
40-2-1	Interior is excessively dirty. (Excessive trash or dirt)

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**