REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 3/26/2014 Time: 11:07 AM

Name of School Corporation: DELAWARE COMM. SCHOOL CORP. Corp ID: 181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRAPSKH49A674248License Number:76531Bus Number:1Make of Body:IC Corporation Year:2009Make of Chassis:IC Corporation Year:2009

Bus Type: Mileage: Unknown

Inspection Status: A Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description