

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/8/2014	<b>Time:</b> 9:41 AM
<b>Name of School Corporation:</b> HANOVER COMM. SCHOOL CORP.		<b>Corp ID:</b> 454580
<b>Address of School Corporation:</b> 14525 Wicker		
<b>City:</b> Cedar Lake	<b>Zip:</b> 46303	<b>County Number:</b> 45
<b>VIN:</b> 1BABNCKA55F226762	<b>License Number:</b> 13964	<b>Bus Number:</b> 5
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2004	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2004	<b>Make of Chassis:</b> Blue Bird Corporation	<b>Year:</b> 2004
<b>Bus Type:</b> D	<b>Mileage:</b> Unknown	
<b>Inspection Status:</b> O	<b>Inspected By:</b> David Eggers	<b>PE:</b> 5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-1	There are loose, broken, or missing mountings
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
61-2-1	Two (2) or more taillights or brake lights do not function

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.