REPORT OF SCHOOL BUS INSPECTION

9:41

2004

Time: Annual Date: 4/8/2014 Inspection: AM HANOVER COMM. SCHOOL CORP. 454580 Name of School Corporation: Corp ID: **Address of School Corporation:** PO Box 645 County City: Cedar Lake Zip: 46303 45 Number: License VIN: 1BABNCKA55F226762 13964 Bus Number: Number:

Make of Blue Bird Blue Bird Year: 2004 Make of Body: Year: Corporation Chassis: Corporation

Bus Type: D Mileage: Unknown

Inspection Inspected 0 PE: David Eggers 5191 Status: By:

Violations - Rejected

Type of

Inspection Code Description

51-1-1 There are loose, broken, or missing mountings

12-1-1 Clearance light is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

Inspection Code Description

61-2-1 Two (2) or more taillights or brake lights do not function

Bus Type Description

Type D School Bus - A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.