## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/8/2014Time:9:24 AMName of School Corporation:HANOVER COMM. SCHOOL CORP.Corp ID:454580

Address of School Corporation: PO Box 645

City:Cedar LakeZip:46303County Number:45VIN:4DRBUAAN68B499587License Number:4952Bus Number:8Make of Body:IC Corporation Year:2008Make of Chassis:IC Corporation Year:2008

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: David Eggers PE: 5191

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

The first aid kit is not properly filled.
The seat belt cutter is not secured

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.