

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/11/2014	Time: 9:56 AM
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS		Corp ID: 475075
Address of School Corporation: 595 Stars Blvd		
City: Bedford	Zip: 47421	County Number: 47
VIN: 1C9CAN489SR493547	License Number: 14093	Bus Number: A6
Make of Body: Carpenter	Year: 1994	Make of Chassis: Carpenter
		Year: 1994
Bus Type: C	Mileage: Unknown	
Inspection Status: O	Inspected By: Travis Coryea	PE: 5892

Violations - Rejected

Inspection Code **Description**

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Reflective glass is cracked, broken, or missing.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.