

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|----------------------------|------------------------|------------|-------------------------|---------|
| Type of Inspection: | Post-Crash Inspection | Date: | 4/15/2014 | Time: | 8:30 AM |
| Name of School Corporation: | BLOOMFIELD SCHOOL DISTRICT | Corp ID: | 282920 | | |
| Address of School Corporation: | PO Box 266 | | | | |
| City: | Bloomfield | Zip: | 47424 | County Number: | 28 |
| VIN: | 1GDL7T1C1XJ515821 | License Number: | B897D | Bus Number: | 11 |
| Make of Body: | Blue Bird Corporation | Year: | 2000 | Make of Chassis: | GMC |
| Bus Type: | C | Mileage: | Unknown | | |
| Inspection Status: | O | Inspected By: | Mark Raper | PE: | 6473 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 69-1-2 | There are intersecting cracks in the windshield area covered by the wipers |
| 69-1-4 | There is cracked glass to the immediate right or left of the driver |
| 69-1-3 | There are breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side |
| 69-1-6 | There is cloudiness which extends two (2) inches from the top or side of any glass; or more than three (3) inches from the bottom of the windshield; or more than five (5) inches from the bottom of any window |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.