

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/15/2014	Time:	8:30 AM
Name of School Corporation:	BLOOMFIELD SCHOOL DISTRICT	Corp ID:	282920		
Address of School Corporation:	PO Box 266				
City:	Bloomfield	Zip:	47424	County Number:	28
VIN:	1GDL7T1C1XJ515821	License Number:	B897D	Bus Number:	11
Make of Body:	Blue Bird Corporation	Year:	2000	Make of Chassis:	GMC
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Mark Raper	PE:	6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-2	There are intersecting cracks in the windshield area covered by the wipers
69-1-4	There is cracked glass to the immediate right or left of the driver
69-1-3	There are breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
69-1-6	There is cloudiness which extends two (2) inches from the top or side of any glass; or more than three (3) inches from the bottom of the windshield; or more than five (5) inches from the bottom of any window

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.