

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/16/2014	Time: 12:37 PM
Name of School Corporation: MARQUETTE HIGH SCHOOL	Corp ID: 71002Z	
Address of School Corporation: 306 W 10th St.		
City: Michigan City	Zip: 46306	County Number: 46
VIN: 1GBHG31R6Y1201361	License Number: b872aa	Bus Number: 1
Make of Body: Chevrolet	Year: 2000	Make of Chassis: Corbeil
		Year: 2000
Bus Type:	Mileage: Unknown	
Inspection Status: O	Inspected By: Nathan Sherer	PE: 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
49-2-1	There is no seat belt cutter in the vehicle.

Bus Type Description