

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/16/2014 Time: 12:37 PM
Name of School Corporation: MARQUETTE HIGH SCHOOL Corp ID: 71002Z
Address of School Corporation: 306 W 10th St.
City: Michigan City Zip: 46306 County Number: 46
VIN: 1GBHG31R6Y1201361 License Number: b872aa Bus Number: 1
Make of Body: Chevrolet Year: 2000 Make of Chassis: Corbeil Year: 2000
Bus Type: Mileage: Unknown
Inspection Status: O Inspected By: Nathan Sherer PE: 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
49-2-1	There is no seat belt cutter in the vehicle.

Bus Type Description