

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	4/24/2014	<b>Time:</b>	10:08 AM
<b>Name of School Corporation:</b>	SOUTH HENRY SCHOOL CORPORATION			<b>Corp ID:</b>	333415
<b>Address of School Corporation:</b>	6972 SR 103				
<b>City:</b>	Straughn	<b>Zip:</b>	47397	<b>County Number:</b>	33
<b>VIN:</b>	1BAKGCPH29F262012	<b>License Number:</b>	32270	<b>Bus Number:</b>	18
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	B	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
15-1-1	There are leaks from the differential, pinion seal, or either rear wheel seal.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**