

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                        |                        |           |                         |                |              |      |
|---------------------------------------|------------------------|------------------------|-----------|-------------------------|----------------|--------------|------|
| <b>Type of Inspection:</b>            | Annual                 | <b>Date:</b>           | 4/16/2014 | <b>Time:</b>            | 10:42 AM       |              |      |
| <b>Name of School Corporation:</b>    | GREATER CLARK CO SCHLS |                        |           | <b>Corp ID:</b>         | 101010         |              |      |
| <b>Address of School Corporation:</b> | 301 E 11th St          |                        |           |                         |                |              |      |
| <b>City:</b>                          | Jeffersonville         | <b>Zip:</b>            | 47130     | <b>County Number:</b>   | 10             |              |      |
| <b>VIN:</b>                           | 4DRBUAAP2CB591614      | <b>License Number:</b> | 677       | <b>Bus Number:</b>      | 123            |              |      |
| <b>Make of Body:</b>                  | IC Corporation         | <b>Year:</b>           | 2012      | <b>Make of Chassis:</b> | IC Corporation | <b>Year:</b> | 2012 |
| <b>Bus Type:</b>                      | B                      | <b>Mileage:</b>        | Unknown   |                         |                |              |      |
| <b>Inspection Status:</b>             | A                      | <b>Inspected By:</b>   | Troy Boyd | <b>PE:</b>              | 5171           |              |      |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**