

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/1/2014	<b>Time:</b> 9:21 AM
<b>Name of School Corporation:</b> BLOOMFIELD SCHOOL DISTRICT	<b>Corp ID:</b> 282920	
<b>Address of School Corporation:</b> PO Box 266		
<b>City:</b> Bloomfield	<b>Zip:</b> 47424	<b>County Number:</b> 28
<b>VIN:</b> 1GBJG31U851187786	<b>License Number:</b> 65625	<b>Bus Number:</b> 3corp
<b>Make of Body:</b> Mid Bus, Inc. <b>Year:</b> 2006	<b>Make of Chassis:</b> Carpenter	<b>Year:</b> 2006
<b>Bus Type:</b>	<b>Mileage:</b> Unknown	
<b>Inspection Status:</b> A	<b>Inspected By:</b> Mark Raper	<b>PE:</b> 6473

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description