REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/7/2014	**Time:**	2:13 PM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			**Corp ID:**	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	**Zip:**	47140	**County Number:**	13
VIN:	1GB3G2BGXC1107641	**License Number:**	C758000	**Bus Number:**	87
Make of Body:	Chevrolet **Year:** 2012	**Make of Chassis:**	Chevrolet	**Year:**	2012
Bus Type:		**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Travis Coryea	**PE:**	5892

Violations - Rejected

Inspection Code	Description
19-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code	Description

Bus Type Description