REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/8/2014	**Time:**	12:00 PM
Name of School Corporation:	NORTH NEWTON SCHOOL CORP.			**Corp ID:**	565945
Address of School Corporation:	PO Box 8				
City:	Morocco	**Zip:**	47963	**County Number:**	56
VIN:	4DRBVAAN69A649766	**License Number:**	31615	**Bus Number:**	13
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
27-1-2	The first aid kit is not properly filled.
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description
49-2-1	There is no seat belt cutter in the vehicle.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.