

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 5/9/2014 **Time:** 9:05 AM
Name of School Corporation: NORTH VERMILLION COMM SCH CORP **Corp ID:** 838010
Address of School Corporation: 5551 N Falcon Dr
City: Cayuga **Zip:** 47928 **County Number:** 83
VIN: 1GBJG312771164694 **License Number:** 72453 **Bus Number:** 17
Make of Body: Mid Bus, Inc. **Year:** 2007 **Make of Chassis:** Chevrolet **Year:** 2007
Bus Type: **Mileage:** Unknown
Inspection Status: O **Inspected By:** Tyler VanNess **PE:** 7583

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
10-1-1	A parking brake lever is not allowed, a plastic/composite material allowing the parking brake knob to be larger and easier to pull is allowed.

Violations - Out of Service

Inspection Code Description

Bus Type Description