

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 5/9/2014      **Time:** 9:05 AM  
**Name of School Corporation:** NORTH VERMILLION COMM SCH CORP      **Corp ID:** 838010  
**Address of School Corporation:** 5551 N Falcon Dr  
**City:** Cayuga      **Zip:** 47928      **County Number:** 83  
**VIN:** 1GBJG312771164694      **License Number:** 72453      **Bus Number:** 17  
**Make of Body:** Mid Bus, Inc.      **Year:** 2007      **Make of Chassis:** Chevrolet      **Year:** 2007  
**Bus Type:**      **Mileage:** Unknown  
**Inspection Status:**       **Inspected By:** Tyler VanNess      **PE:** 7583

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
10-1-1	A parking brake lever is not allowed, a plastic/composite material allowing the parking brake knob to be larger and easier to pull is allowed.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description