

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 5/9/2014 **Time:** 7:58 AM
Name of School Corporation: SEYMOUR COMMUNITY SCHOOLS **Corp ID:** 363675
Address of School Corporation: 1638 S Walnut St
City: Seymour **Zip:** 47274 **County Number:** 36
VIN: 4DRBUAAN9BB335077 **License Number:** 74352 **Bus Number:** 26
Make of Body: IC Corporation **Year:** 2011 **Make of Chassis:** IC Corporation **Year:** 2011
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.